

LX Series

Indicator Needle Type Shore Hardness Tester

LX-A	 LX-A-1 LX-A-2
LX-C	 LX-C-1 LX-C-2
LX-D	 LX-D-1 LX-D-2

1.Application:

Type A: Applicable to general rubber, synthetic rubber, vulcanized rubber, soft rubber, leather, wax, etc.

Type C: Applicable to the hardness test of rubber microporous material.

Type D: Applicable to hard rubber, hard resin, acrylic, glass, cushiony plastic cement, printing plates, fiber, etc.

2.Major Performances:

Shaw rubber hardness gauge is an apparatus to measure vulcanized rubber and plastic products. This apparatus has three models of Type A, Type C and Type D and each model is subdivided into two types of single pointer and double pointer.

Type A and D respectively are applicable to the testing of low and medium hardness, and high-hardness materials.

Type C applies to the testing of microporous material which is used to make shoes, with compression rate 50 percent, stress 0.049 MPa or above, and this kind of material is made of rubber plastic and has blister in plastic.

This hardness gauge conforms to the regulations of GB/T531-99, GB2411-80, HG/T2489-93, JJG304-2003.

3.Specifications:

Types	LX-A		LX-C		LX-D	
Indicator Needle	Single	Double	Single	Double	Single	Double
Model	LX-A-1	LX-A-2	LX-C-1	LX-C-2	LX-D-1	LX-D-2
Test Range	0-100HA		0-100HC		0-100HD	
Available Test Range	10-90 HA		10-90 HC		10-90 HD	
Resolution	1HA		1HC		1HD	
Pressure Head Size	0.79mm		SR2.5mm		SR0.1mm	
End pressure of Pressure Head	0.55N-8.06N		0.55N-8.06N		0-44.5N	
Stroke	0-2.5mm					
Dimension	115*60*25mm					
Apparatus Weight	0.16 KG					

LX Series Digital Display Shore Hardness Tester

LX-A	LX-C	LX-D
		

1.Overview:

Shore Hardness Tester is an apparatus to measure vulcanized rubber and plastic products.

This apparatus has three models of **LX-A**, **LX-C** and **LX-D**.

LX-A and **LX-D** respectively are applicable to the testing of low and medium hardness, and high-hardness materials.

LX-C applies to the testing of microporous material which is used to make shoes, with compression rate 50 percent, stress 0.049 MPa or above, and this kind of material is made of rubber plastic and has blister in plastic.

This hardness gauge conforms to the regulations of GB/T531, GB2411, HG/T2489, JB6148.

2.Main Technical Parameters:

Model	LX-A	LX-C	LX-D
Measuring Range	0-100°		
Measuring Error	Within 20-90°,the error is $\leq \pm 1^\circ$		
Resolution	0.1°		
Pressure Needle Range	0-2.5mm		
End Pressure Of Pressure Head	Type A and C: 0.55N-8.05N Type D: 0-44.5N		

3.Using Methods:

When using sample, one should place the sample in the solid plane, hold the hardness gauge, keep the pressure needle at a distance of at least 12 mm from the edge of the sample, smooth enough pressure in the pressure on the sample, and smoothly press on the sample to a full extent. until pressed to a full extent and contact the sample completely, then read the calibration value within one second.

At measuring points which are at least 6 mm away from each other, measure hardness values for five times, and calculate the average value (for microporous material, the distance between the measuring points should be at least 15 mm).

In order to keep the stability of conditions and improve the accuracy of determination, one should install the hardness gauge on the same type of the measuring shelf from a complete production network.

4.Using Instructions:

- 4.1.Before using,please check the hardness tester should be display “00.0” in free state(if don’t display,you can press “ZERO” button).Place the hardness gauge on glass plate, and the pointer should direct at a 100 ± 1 degree angle (the end of pressure needle and the bottom surface of pressure foot should be closely in contact with the glass surface) If the pointer doesn’t point to the zero position, it cannot be used, either.It’s better to send it back to the factory for adjustment.
- 4.2.Type D hardness tester on reference plane to check the zero position,Under the heavy load,the hard pressure head is easy to pressed reference plane,so must be put on standard gauge block on the reference plane,when operating with hardness tester,the indenter alignment gage block center hole,then pressed hardness tester,when the indenter foot completely stitching with standard gauge block and reference plane,the hardness tester should be display 10 ± 1 HD(Gauge block thickness 2.25 ± 0.0003 mm is equal to hardness tester into 10HD pressure depth), if can’t display accurately,the hardness tester also cannot use.
- 4.3.Rubber sample shall be prepared according to the requirements of GB/T531;plastic sample shall be prepared according to the requirements of GB2411;Rubber microporous materials sample shall be prepared according to the requirements of HG/T2489.
- 4.4.Before the test,rubber sample shall be prepared according to the requirements of GB/T2941, GB/T2918 in the laboratory standard temperature to test.
- 4.5.When measuring the sample, A-type hardness gauge’s value is more than 90 degrees, it is recommended that one should use D-type hardness gauge. When using D-type hardness gauge, the value is below 20 degrees, it is recommended that one should use A-type hardness gauge. When A-type hardness gauge’s value is 10 degrees, it is not accurate, and the measurement result can not be used.
- 4.6.After complete using the hardness gauge, it should be wiped clean and put into the device box, and stored in dry place to prevent damp. The measurement shelf should be wiped frequently and be coated with a little anti-rust oil to prevent it from rusting, moreover add No. 20 oil to the flexible parts.

TH200 Digital Display Shore Hardness Tester (ShoreA)



1.Application:

TH200 Digital Display Shore Hardness Tester (Shore A) is applied to test the soft rubber, plastics and such substances. This hardness tester integrating measurement device and data processing, with the merits of compact, accurate measurements and easy to carry, beautiful modelling, light weight and easy to operate.

2.Specifications:

Model	TH200
Test Scale Available	Shore A
Standards	DIN 53505, ASTM D2240, ISO 7619, JIS K7215.
Display	Hardness Result, Average Value, Max Value(Peak Value Lock), Battery Indication.
Measuring Range	0~100HA
Measurement Deviation	Within 20~90 HA, Error $\leq\pm 1$ HA
Display Resolution	0.1 HA
Operating Temperature	0~40 °C
Power Requirements	3×1.55V Button Batteries
Dimensions	173mm*56mm*42mm
Weight	233g

3.Features:

- 3.1. The maximum latches, average automatic calculation and under-voltage alarm function.
- 3.2. The machine carries communication cable, connection with it, can carry out data communication with the computer.
- 3.3. Automatically switch off. 3.4. Bright & clear LCD display. 3.5. With operating stand.

4.Basic Configuration:

- 4.1. Button Batteries 3×1.55V
- 4.2. Hardness Tester Operating Stand.
- 4.3. RS232 Communication Cable.

TH210 Digital Display Shore Hardness Tester (Shore D)



1.Application:

TH210 Digital Display Shore Hardness Tester (Shore D) is applied to test the hardness of the Hard plastic (such as thermoplastic, hard resin, nylon, and organic glass etc.), hard rubber and other related chemical products(such as anti-corrosion coating materials, flame retardant materials, paint, etc.). This hardness tester measurements accurate and easy to carry, beautiful modeling and easy to operate.

2.Specifications:

Model	TH210
Test Scale Available	Shore D
Measuring Range	0~100HD
Measurement Deviation	Within 20~90 HD, Error $\leq$ ±1HD
Display Resolution	0.2 HD
Power Requirements	3*1.55V Button Batteries OR 4.5 V AC/DC Power Adapter
Dimensions	173mm*56mm*42mm
Weight	233 g

3.Features:

- 3.1.The maximum latches, average automatic calculation and under-voltage alarm function.
- 3.2.Automatically switch off.
- 3.3.Bright & clear LCD display.
- 3.4.With operating stand.

4.Basic Configuration:

- 4.1.TH210 Mainframe.
- 4.2.Button Batteries.
- 4.3.Hardness Tester Operating Stand.